

Technical Bulletin



Replace Slave Cylinder to Eliminate Hard Pedal/Release Problems

**Vehicles: 1993-98 Ford Bronco, Explorer, F-Series, Ranger;
Mazda B2300, B3000, B4000, Navajo**

**LuK Part Numbers: 07-093, 07-096, 07-097, 07-098, 07-099,
07-117, 07-128, 07-130, 07-140, 07-141, 07-903,
07-905, 07-909, LSC003**

Hard pedal/release problems may result from leaks in the internal seal of the slave cylinder. Replace the slave cylinder with LuK part #LSC003 which contains an upgraded seal to prevent leakage.

For additional information, refer to Ford bulletin #97-22-17.

For application, diagnostic or installation questions, call the LuK Technical Hotline at 800-274-5001, 8:00 a.m. to 5:00 p.m. ET Monday through Friday, or check online at www.lukclutch.com.

Schaeffler Group Automotive

United States

5370 Wegman Drive
Valley City, OH 44280
Phone 800 274 5001
Fax 330 273 3522

Canada

2871 Plymouth Drive
Oakville, ON L6H 5S5
Phone 800 261 8111
Fax 905 829 9034

Web www.lukclutch.com

Reemplace El Cilindro Esclavo para Eliminar Los Problemas de Pedal Duro/liberación

Vehículos: 1993-98 Ford Bronco, Explorer, F-Series, Ranger;
Mazda B2300, B3000, B4000, Navajo

Números de Parte LuK: 07-093, 07-096, 07-097, 07-098,
07-099, 07-117, 07-128, 07-130, 07-140, 07-141,
07-903, 07-905, 07-909, LSC003

Los problemas de pedal duro/liberación pueden resultar de las fugas en el sello interno del cilindro esclavo. Reemplace el cilindro esclavo con la parte de LuK #LSC003 que contiene un sello actualizado para prevenir fugas.

Para información adicional, refiérase al boletín de Ford #97-22-17.

Para preguntas sobre aplicaciones, instalación o diagnóstico, llame a la línea rápida de servicio técnico de LuK al 800-274-5001, de 8:00 a.m. a 5:00 p.m. de lunes a viernes, o visítenos en línea en www.lukclutch.com.

Remplacer le cylindre récepteur pour éliminer les problèmes de débrayage et de pédale dure

Véhicules: 1993-98 Ford Bronco, Explorer, F-Series, Ranger;
Mazda B2300, B3000, B4000, Navajo

Pièces LuK n^{OS}: 007-093, 07-096, 07-097, 07-098, 07-099,
07-117, 07-128, 07-130, 07-140, 07-141, 07-903,
07-905, 07-909, LSC003

Les problèmes de pédale dure et de débrayage peuvent être causés par des fuites du joint interne du cylindre récepteur. Remplacer le cylindre récepteur par la pièce LuK LSC003 qui comporte un joint amélioré pour prévenir les fuites.

Consulter le bulletin Ford 97-22-17 pour des informations supplémentaires.

Pour toute question en matière d'application, de diagnostic ou d'installation, téléphoner au soutien technique LuK, au 800-274-5001, du lundi au vendredi de 8h à 17h HE, ou consulter le site www.lukclutch.com.