

Fits: GM 6T40/45 2008- UP

Brand new steel plates that have been designed by to save your 6T40/45, 4-5-6 Drum. Also includes an extra thin steel plate in case your piston hemline has worn out.

Directions:

Step 1: Remove bottom waved plate and backing plate from damaged drum. You will notice these are the very last bottom plates.

Step 2: After removal of OE Drum plates (Backing Plate and waved plate) place waved plate first and backing plate afterwards. This will cover damaged area and will fix the problem.

Step 3: Depending on wear and tear of piston hemline, you may use our 0.8 mm thin steel plate. If your piston hemline is not very worn out, there is no need for additional steel plate.

(PLEASE NOTE THAT IF YOU'RE PISTON HEMLINE IS NOT WORN OUT, THERE IS NO NEED FOR EXTRA PLATE.)

Step 4: You may then place the rest of frictions and steel plates as usual.

Below you will find our solution to fixing the problem forever.



