


Manual Valve

Part No.

41750-03


NOTE: Not recommended for some Hyundai applications. Do not use with .218" (5.5mm) ball in pump. Valve is calibrated to work with all units with .312" (8mm) ball in pump.

Mitsubishi KM 4-Speeds



1. Remove OE manual valve from valve body and discard.
2. Replace with Sonnax manual valve.

Sonnax Manual Valve



OE Manual Valve

