

Instructions

GM 4L60

Throttle Valve Plunger Valve Kit

Part No. 77966-94K

- Sleeve
- Plunger
- Spring

NOTE: Replacement for OE plungers with "94" code.





1. Disassembly

- a. Remove OE retaining pin and save for reuse.
- b. Remove and discard OE sleeve, plunger and spring.

2. Installation & Assembly

- a. Insert plunger and spring into sleeve in orientation shown.
- b. Install sleeve/plunger/spring assembly into valve bore, just far enough to reinstall OE retaining pin.