

Attention Rebuilder/Installer



BOSCH
Invented for life

Replacement Ford 6F50/6F55 Transmission Solenoid Body Codes Needed for Vehicle Powertrain Control Module Update

It's recommended to follow the vehicle manufacturer's service instructions for the application when replacing a transmission solenoid body.

If required to update the vehicle Powertrain Control Module (PCM) using a diagnostic / scan tool, the installer will need two (2) codes – each marked on the solenoid body beneath a 2D matrix as **shown at right**.

A tag on top of the transmission contains the original Strategy and Body ID codes. **This tag may be covered with a tag that includes the new codes from the replacement Solenoid Body** – see example shown below (adhesive label is approximately 35mm x 70mm).


**Replacement Solenoid Body
F00HZ30038**

SOL STRATEGY: (13-digit code)

SOL BODY ID: (7-digit code)

**Tag with new codes from the
replacement Solenoid Body**

F00HZ30038 – Replacement Ford 6F50/6F55 Transmission Solenoid Body



For further information, consult the vehicle manufacturer's service instructions.