

Heavy Duty Input Shaft

Part No.

34670-01

OE Part No. 24222184

GM 4L80-E, 4L85-E



NOTE: Do not remove spiral ring from O.D. carrier splines.